

7/1



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2972749 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
07-01-2017

No new defects noted in area

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	7/5/17
Target Finish:	7/5/17
Actual Start:	7/1/17
Actual Finish:	7/1/17
Report Date:	6/27/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270-#####-0901-#####-#####-####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48481

Job Plan:	2961
Job Desc:	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2972749 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
07-01-2017

No new defects noted in area

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD		



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2972749 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
07-01-2017

No new defects noted in area

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	AREPAIR		TSCHISLI						N		08:00	00:00	210.32
	AREPAIR		MPOLLAF						N		08:00	00:00	210.32
Total Actual Labor:													420.64



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2972749 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
07-01-2017

No new defects noted in area

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

Date Completed

Completed By

Supervisor

Daily Track Inspection

Date 7-1-17 Page 1 of 1

WO# 297 2749

To LINT - Buell

[illegible]

Comments

[illegible]

NO _____

NO 4

Reason for Inspection _____

T. Schuch
Track Inspectors Signature

Jasman Reaver
Supervisory Certification

7/3/17
Date

Light Rail MOW
Daily Track Inspection

Name T SCHISLER Date 7-1-17 Page 1 of 1

Watchman M. Poulard WO# 297 2749

Inspection From Cook To LINT - BUI

[illegible]

Items

Comments

[illegible]

Were switches in area inspected? YES X NO

Is this a Special Inspection? YES _____ NO ✓

Reason for Inspection _____

T. Schuch
Track Inspectors Signature

Jamie Reaver
Supervisory Certification

7/3/17
Date